	Туре	L#	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition
1	BRS	LI	802	differential adj2 signal and single adj end\$ adj2 signal	USPAT; EPO; JPO; DERW ENT	2002/06/18 18:05		Truncation overflow.
2	BRS	L2	4	1 and signal near determinat\$	USPAT; EPO; JPO; DERW ENT	2002/06/18 18:05		
3	BRS	L3	798	1 not 2	USPAT ; EPO; JPO; DERW ENT	2002/06/18 18:05		
4	BRS	L4	546	differential adj2 signal same single adj end\$ adj2 signal	USPAT; EPO; JPO; DERW ENT	2002/06/18 18:07		Truncation overflow.
5	BRS	L5	0	4 not 1	USPAT ; EPO; JPO; DERW ENT	2002/06/18 18:07		
6	BRS	L6	544	4 not 2	USPAT; EPO; JPO; DERW ENT	2002/06/18 18:08		
7	BRS	L7	0	6 and signal near determination	USPAT; EPO; JPO; DERW ENT	2002/06/18 18:08		
8	BRS	L8	0	6 and signal near determinat\$	USPAT; EPO; JPO; DERW ENT	2002/06/18 18:09		
9	BRS	L9	59	6 and clock near3 generat\$	USPAT; EPO; JPO; DERW ENT	2002/06/18 18:11	li A s.	Truncation overflow.
10	BRS	L10	1	"6137340",PN.	USPAT	2002/06/18 18:13		***************************************
11	BRS	L11	1	"6040731".PN.	USPAT	2002/06/18 18:13		***************************************

	Туре	L#	Hits		DBs	Time Stamp	Comments	Error Definition
12	BRS	L12	1	"6028454".PN.	USPAT	2002/06/18 18:14		
13	BRS	L13	1	"5942922".PN.	USPAT	18:14		
14	BRS	L14	1		[2002/06/18 18:14		
15	BRS	L15	1	"5798660".PN.	USPAT	2002/06/18 18:15		